


SET-UP INSTRUCTIONS FOR

STAHL'S[®] EZ-WEEDING[™] TABLE



CAREFULLY
Unbox your Stahls[®]
EZ-Weeding Table[™] and
place it on a secure
surface.



USING the four (4)
bolts and nuts provided,
attach the material
hold-down bracket to
the table.



SECURE the plug to the
weeding table and plug
into a 110 volt power
outlet.



TURN ON the EZ-
Weeding Table by using
the power rocker switch
located on the left side
of the table.



SELECT the heat
temperature.
Low- 110 degrees
Medium- 120 degrees
High- 130 degrees
The temperature light
will turn GREEN when
proper temperature is
reached.

